

Ref 1009



AQUASTAR 65'
Built 2006
Maintained to a very high Standard

- Engines Twin Caterpillar C18 1000 H.P each
- Hydraulic 20hp Bow and stern thrusters with hand held remote
- Hydraulic stabilisers
- Second windlass and bow roller anchor and chain to foredeck
- Fuel tanks 2000 gallons
- Water maker
- 1 E series to nav table
- A.V equipment
- Independent battery supply and cables, inverters transform
- 24v to 12v for AV supply
- Fwd facing echo sounder and repeater
- Sat TV G6 Dome and box
- Navtex
- Anchor alarm depth to aft-cabin
- Anchor chain counter
- Flybridge 309 crane 250 kilo
- Air-con 100,000 B.T.U
- 50 amp shore connection
- Full canvas enclosure
- Bimini
- Dual filters to main engines

- Oil change system
- 2 cameras to side decks, 1 aft, 1 engine room and wire up
- DSM 300 digital sounder module to give fishfinder type display to all screens
- Generator spares kit
- Second Generator
- Wind repeater to both helms
- C/D surround sound system
- C/D system to flybridge
- 17" colour T.V flat screen
- Fwd cabin 15" T.V D.V.D
- Mid port 15" TV DVD
- Saloon TV 37"
- Garbage compactor
- Drinks fridge to flybridge, drawer type
- Dishwasher
- Dehumidifier in utility
- 2 extra fridges under helm seat box
- Pull out ironing board to fwd cabin
- Map to aft-deck table
- Hydraulic deck winches
- Hydraulic trim planes heavy duty
- Capstans to starboard
- Teak laid side and foredeck
- Wood finish Bird's eye Maple
- Teak deck to after end of flybridge
- Child gates to side decks
- Door to galley port side
- 2 six man life rafts in stainless steel frames and hydrostatic release
- Hydraulic Bathing platform fitted 2011
- Twin Hydraulic Biminis fitted 2011

Asking price
Lying

£950,000.00 VAT paid
Croatia

In this case we are acting as Brokers only. Vendor is not selling in the course of Business. Whilst every care has been taken in their preparation, the correctness of these particulars is not guaranteed. The particulars are intended only as a guide and they do not constitute a term of any contract. A prospective buyer is strongly advised to check the particulars and wherever appropriate, at his own expense to employ a qualified marine surveyor to carry out a survey and/or have an engine trial conducted.

E&OE